

Exhibit 3: Site Photographs



Looking from the beginning of the trail to the temporary bridge over San Vicente Creek. The banks of the creek are eroding at a rate that threatens the stability of the bridge.



Looking back at the beginning of the trail, after crossing the temporary bridge. The Reserve parking lot is across the road pictured at the top of the incline.

Exhibit 3: Site Photographs



Looking from the end of the temporary bridge, walking towards the ocean. Improvements are needed to make this trail ADA-compliant.



The proposed Coastal Trail will be built along existing dirt trails, portions of which require little improvement.

Exhibit 3: Site Photographs



The end of this proposed segment of the Coastal Trail is pictured above, running between the two downed logs and intersecting Cypress Avenue. Hikers can walk around the traffic barrier to access the Bluff Trail, which loops back along the oceanside cliffs to the Fitzgerald Marine Reserve parking lot. Because the cliffs are highly erosive, the Bluff Trail cannot be improved to meet ADA standards. Users with limited mobility can return to the parking lot via the trail on which they came.